



### SITE CLOSURE REPORT

WORTH INDUSTRIES 3416 SANDY RIDGE ROAD COLFAX, NORTH CAROLINA

**AUGUST 13, 1995** 

LEGACY ENVIRONMENTAL SERVICES, INC.





## LEGACY ENVIRONMENTAL SERVICES, INC.

P.O. Box 4560, Greensboro, NC 27404-4560, Phone (910) 316-0452, FAX (910) 299-1961

August 13, 1995

Mr. Charles Whisenant Shamrock Corporation PO Box 16247 Greensboro, North Carolina 27416

Reference:

Site Closure Report

Worth Industries 3416 Sandy Ridge Road Colfax, North Carolina

Dear Mr. Whisenant,

On October 5, 1993, a soil assessment report was issued and received by Guilford County Emergency Services. In accordance with Guilford County's November 1, 1993 letter a monitor well was installed and the groundwater tested for isopropyl acetate. According to our records the water quality data was faxed to Guilford County on December 31, 1993.

Legacy Environmental Services, Inc. was contracted by Shamrock Corporation to report site closure activities. The following measures have been performed at this facility:

- The USTs located at this facility were removed from the site on 1/20/93. In order to mitigate fire and safety hazards and to prevent further release, all regulated substances were removed from the UST. Figure 1 illustrates the location of the project site. A copy of the GW/UST-2 Site Investigation Form is included as Attachment A. A UST closure report was previously submitted.
- On January 17, 1994, an initial groundwater testing report was prepared by Legacy and submitted to Arnold Equipment. Testing of the groundwater via a monitor well did not reveal any detectable levels of isopropyl acetate; a copy of this report is in Attachment B.
- On July 5, 1995, the DEM issued a certificate of approval (Attachment C) for disposal of approximately 40 cubic yards of petroleum distillate contaminated soil resulting form the permanent closure of the USTs at this site.
- This report was conducted under the supervision of a Professional Engineer; this certification is included as Attachment D. We recommend forwarding this report to the Guilford County Health Department at the following address for a final determination:

Ms. Kelly Gage Guilford County Department of Public Health 301 N. Eugene Street Greensboro, NC 27401

This report has been prepared for the exclusive use of Shamrock Corporation for the specific application to the referenced site located in Colfax, North Carolina. The evaluation was conducted based on the scope of work and level of effort desired by the client and with resources adequate only for the scope of work. Our findings have been developed in accordance with generally accepted standards for site closures in the State of North Carolina, available information and our professional judgement. No other warranty is expressed or implied. The data presented in this report are indicative of conditions at the precise locations sampled and at the time the sample was collected. Additionally, the data obtained from the samples would be interpreted as meaningful with respect to the parameters in the laboratory reports. No additional information can be logically inferred from this data.

Mr. Whisenant, please contact our office if you have any questions concerning this report.


Sincerely,

Ed Setzer, Senior Chemist

Legacy Environmental Services, Inc.

R95-188

**FIGURES** 



# ATTACHMENT A


IAN IN	OR ANKS IN Site Investigation Report For Permit OR ANKS IN SEE MAP ON REVERSE SIDE OF OWNER'S COPY (PINK) OFFICE ADDRESS].						y of the facility's location.  S  FOR REGIONAL  C			State Use Only I.D. Number Date Received			
	Complete and return within (30) days following completion of site investigation.												
I. Ownership of Tank(s)													
	Shamrock Corporation Worth Industries												
P.C	C after Names (Corporation Included Public Agency, or Other Entry) P.O. BOX 16247							Facility Name or Company					
Sireet A	Address Sensboro	, NC 27405				Facility ID * (if available) 3416 Sandy Ridge Road							
	XXXXX G					Street Address of State Road  XXXXXXX Guilford COLFAX NC 27235							
	9/574-4					County City Zip Code							
Area C	009	Telephone Num	nber	III.' Cor	otaet G	Area C	code			chone Number			
		nisonant /	Dir. of	_				<u> </u>		919/574-4200			
	Contractor							207 GG	Tele	prone No. (Area Code) 27419 919/299-5220			
	(	Name)	/A	ddraeel		<u> </u>				phone No. (Area Code)			
·	(	Name)		<u>le. N</u>	<u></u>		<del></del>			19/996-2841 phone No. (Area Code)			
		V. UST. Informatio	nr i 🖆 🚅 🖟 i i i				r Cand		,	VL Additional Information Required			
Tank No.	Size in Gallons	Tank Dimensions	Läst Contents		vation	Pro	duct	Verble Soil	Contamination				
1	6K	8'0"x16'0"	Iso.P. Acetate		No X	Yes	No X	Yes X	· No	See reverse side of pink copy (owner's copy) for additional information required by			
2	4K	4'0"x24'0"	Ethyl Acetate		х		х		x	N.C DEM in the written report and sketch.			
3	2 <u>K</u>	5'0"x12'2"	Ethyl Acetate		х		x		х				
4	2X	5'0"x12'2"	Ethyl Alcohol	•	X		x		х				
5	2K	5'0"x12'2"	DiOctyl PhTh.		х		х		х				
6	4K	4'0"x24'0"	Gasoline		X		X		x	-			
				VIIL	Check	List	•						
		cal fire marshall			activitie:	s comp	ieted.	1	Artin	Maylant Copy			
	Notify DEM Regional Ciffice before abandumment Removal.  Drain & flush piping into tank.  Remove all product and residuals from tank  Excavate down to tank.  Clean and inspect tank.  Remove drop tube, fill pipe, gauge pipe, vapor recovery tank connections.  ABANDONMENT IN PLACE  Fill tank until material overflows tank openings:  Disconnect and cap or remove vent line  Solid inert material used - specify:								overflows tank opening; gs: remove vent line				
	submersible pumps and other tank fixtures.  Cap or plug all lines except the vent and sil lines.  Purge tank of all product & farmable vapors.  Cut one or more large holes in the tanks. By SAFE EURY TANK Disp.  Backfill the area.  Date Tank(s) Permanently closed:  Date of Change-in-Service:  Services  REMOVAL  Label tank  Dispose of tank in approved manner  Final tank destination:  Safeway Tank Dispose												
i 	Colfax, NC												
	VIII. Certification (Read and Sign)												
1000	i certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete.												
1			wher's authorized representation of Mfg.	tive		Jigi	nature	[]/dia	<u> </u>	1 /3/93			
	GW/UST-2 Rev.7/29/91 White Copy - Regional Office Yellow Copy - Central Office Prix Copy - Owner												

# ATTACHMENT B

## INITIAL GROUNDWATER TESTING SUMMARY REPORT

WORTH INDUSTRIES COLFAX, NORTH CAROLINA

JANUARY 17, 1994





# LEGACY ENVIRONMENTAL SERVICES, INC.

P.O. Box 4560, Greensboro, NC 27404-4560, Phone (910) 316-0452, FAX (910) 299-1961

January 17, 1994

Mr. Roger Brewster Arnold Equipment Company, Inc. PO Box 18207 Greensboro, NC 27419

Reference:

Initial Groundwater Testing Summary Report

Worth Industries Colfax, North Carolina

Dear Mr. Brewster,

Please find enclosed a report summarizing the initial groundwater testing for the former underground storage tank locations at the above referenced facility. The groundwater testing consisted of the installation of one permanent monitoring well located in the vicinity of the former underground storage tanks. On December 28, 1994 field personnel from Legacy mobilized to the site to perform the installation of the monitoring well and sample the groundwater for isopropyl acetate analysis. The results of these activities are summarized herein.

If you have any questions please contact our office.

Sincerely,

Ed Setzer Senior Chemist

c. LES job file P-228

#### TABLE OF CONTENTS

		Page
1.1 1.2 1.3	Introduction	1
<b></b>	Conclusions and Recommendations.	
· .	LIST OF FIGURES	
Monit	oring Well Location	

### **ATTACHMENTS**

Attachment A: Well Construction Record
Attachment B: Analytical Report

Figure 1:

# INITIAL GROUNDWATER TESTING SUMMARY REPORT WORTH INDUSTRIES COLFAX, NORTH CAROLINA

#### 1.1 Introduction

Worth Industries operated six underground storage tanks (USTs) at the site in Colfax, NC. A decision was made by Worth Industries to remove these underground storage tanks in order to comply with the requirements of EPA 40 CFR Part 280. Arnold Equipment Company, Inc. was contracted to conduct this closure project and ensure compliance with all Federal, State and Local regulations. In order to assess the condition of the site and to estimate the extent of contamination, an environmental assessment of the soils surrounding the USTs was performed. As a result of the mild soil contamination discovered during the assessment, Guilford County required the installation of a monitoring well system to investigate possible groundwater contamination.

#### 1.2 Scope of Services

On January 17, 1994 field personnel from Legacy mobilized to the site to install a monitor well system in the area surrounding the USTs. The location of this well (MW-1) is detailed in Figure 1. A water sample was collected and tested for isopropyl acetate as required by Guilford County's November 1, 1993 letter. The well was purged and the groundwater sample was collected using DEM's March 1993 guidelines. The well construction record is included as Attachment A; the analytical results are included as Attachment B.

### 1.3 Conclusions and Recommendations

The analytical testing of the groundwater did not reveal any detectable levels of isopropyl acetate, therefore, the mild soil contamination identified during the UST closure does not appear to be a significant secondary source which could potentially threaten groundwater quality.

We recommend forwarding a copy of this summary report to Guilford County Emergency Services.

er Name (from Section i) WORTH TINDUSTRIES O					or Pages
nk Identification No. (e.g., ABC-123), or bitrarily Assigned Sequential Number (e.g., 1,2,3_)	Tank No.	Tank No.	Tank No.	Tank No.	Tank No. 5
Status of Tank Currently in Use (Mark all that apply 图) Temporarily Out of Use Permanently Out of Use Brought into Use after 5/8/86					
Estimated Age (Years)	6,000	20 4,000	20 2,000	2,000	20
Estimated Total Capacity (Gallons)  Material of Construction	6,000	4,000	2,000	2,000	
(Mark one 2)  Concrete  Fiberglass Reinforced Plastic  Unknown  Cther, Please Specify					
Internal Protection Cathodic Protection (Mark all that apply 31) Interior Lining (e.g., epoxy resins)  None Unknown Other, Please Specify					
External Protection Cathodic Protection (Mark all that apply ©) Painted (e.g., asphaltic) Fiberglass Reinforced Plastic Coated None Unknown					
Other, Please Specify		<del></del>			
(Mark all that apply 12)  (Mark all that apply 12)  Galvanized Steel  Fiberglass Reinforced Plastic  Cathodically Protected  Unknown  Other, Please Specify				,	
1. Constant Constant		<u> </u>	·! ———		<u> </u>
in Greatest Quantity by Volume  (Mark all that apply II)  Dieset  Kerosene  Gasoline (including alcohol blends)  Used Cil  Other, Please Specify  c. Hazardous Substance	BLEND #1284	BLEND #1290			
P!ease Indicate Name of Principal CERCLA Substance		E. ACE.	ETHYL AC	1 ——	·   <del></del>
Chemical Abstract Service (CAS) No. Mark Dox II if tank stores a mixture of substances d. Unknown	108-21-	4 144-78	6 144-78	6 64-17	7 5 117-
Additional information (for tanks permanently taken out of service)	Ī				
a. Estimated date last used (mo/yr) b. Estimated quantity of substance remaining (gal.) c. Mark box (a if tank was filled with inert material (e.g., sand, concrete)	· /	/			/

her Name (from Section I) WORTH INDUSTRIES Lo	cation (from Sect	lon II) COLFA	X, NC	- _ Page No	2 Pages
VI. DESCRIPTION OF UNDERGROUN				aligne y-way the last	
nk Identification No. (e.g., ABC-123), or Ditrarily Assigned Sequential Number (e.g., 1,2,3)	Tank No.	Tank No.	Tank No.	Tank No.	Tank No.
Status of Tank Currently in Use (Mark all that apply 2) Temporarily Out of Use Permanently Out of Use Brought into Use after 5/8/86					
Estimated Age (Years)	15				
Estimated Total Capacity (Gallons)	(2000)4,0	00 REA 2	/ <b>9-93</b>		
Material of Construction Steel (Mark one 図) Concrete Fiberglass Reinforced Plastic Unknown Other, Please Specify					
Internal Protection (Mark all that apply 21) Interior Lining (e.g., epoxy resins) None Unknown Other, Please Specify					
External Protection	<u> </u>	<u> </u>	<u> </u>		
(Marx all that apply 12)  Fiberglass Reinforced Plastic Coated  None  Unknown  Other, Please Specify					
Piping  (Marx all that apply II)  Galvanized Steel  Fiberglass Reinforced Plastic  Cathodically Protected  Unknown  Other, Please Specify					
Substance Currently or Last Stored a. Empty					
in Greatest Quantity by Yolume (Marx all that apply (1))  Ciesel Kerosene Gasoline (including alcohol blends)  Used Cil  Other, Please Specify					
· — Hazardous Substance					
Please Indicate Name of Principal CERCLA Substance		.   ——	.		
OR Chemical Abstract Service (CAS) No. Mark box 2 if tank stores a mixture of substances d. Unknown			-		
: Additional Information (for tanks permanently taken out of service)					
a. Estimated date last used (mo/yr) b. Estimated quantity of substance remaining (gal.) c. Mark box 2 if tank was filled with inert material (e.g., sand, concrete)	/	/ 	/	/	/